

AUSTRALIAN CHEMICALS & COATINGS PTY LTD

69 Quantum Close, Dandenong South VIC 3175 PHONE: (61 3) 9799-9833 FAX: (61 3) 9799-9033

sales@auschem.com.au

A.B.N. 92 884 104 142

NEUTRAL SALT SPRAY REPORT

DATE: 4/06/2025 LAB REQUEST NUMBER: 14174

Process:

• 3 Parts supplied by A&A and 2 parts from TURNER for comparative Neutral Salt Spray testing.

Salt Spray Cabinet Operating Conditions:

Neutral Salt spray test performed according to ASTM B117 Salt used: Sodium Chloride

Salt Concentration	$50 \pm 5 \text{ g/L}$
Pressure	0.07 - 0.17 MPa
Chamber Temperature	35°C
pH (Salt Solution)	6.5 - 7.2
SG (Salt Solution)	1.029 - 1.036
Orientation	70° from the horizontal

HDG Parts were in the salt spray chamber from the 31/03/2025 to the 22/04/2025.

High Build A and A parts were in the salt spray chamber from the 19/03/2025 to the 14/05/2025.

A and A parts were in the salt spray chamber from the 7/04/2025 to the 4/06/2025.


Corrosion Results:


TURNER HDG PARTS: Part 1 has severe white rust by 48 hours and red rust by 528 hours. Part 2 has severe white rust by 24 hours and red rust by 168 hours.


A and A HIGH BUILD: Part 1 and 2, white rust starts developing by 1008 hours. Part 3 has white rust by 24 hours and red rust by 864 hours.


Comments:

Salt Spray Photos:





















Part #2 (A and A – SurTec 704 and SurTec 688)










1008 HOURS

1344 HOURS









Color code:

Green: Pass

Yellow: White Rust Red: Red Rust(Failed)

For prompt processing of orders please Cc: orders@auschem.com.au

